



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Las Cruces
Lease No. 29141
Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....	Temporary Abandon	X

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Federal "A"

March 14, 1960

Well No. 2 is located 1837 ft. from N line and 1650 ft. from E line of sec. 4

SW/4 of NE/4
($\frac{1}{4}$ Sec. and Sec. No.)

19-S
(Twp.)

37-E
(Range)

NMPM
(Meridian)

Eumont
(Field)

Lea
(County or Subdivision)

New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

This well hasn't produced any water, oil or gas in the last several months. As a result the allowable was cancelled. After continued efforts were exhausted to restore production, we wish to temporarily abandon (remove rods, pump & tubing) and leave the casing with a cement plug placed in bottom and top of casing.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company THE ATLANTIC REFINING COMPANY

Address P.O. BOX 1038

DENVER CITY, TEXAS

By N.A. Carr

Title District Superintendent