

N. M. OIL CONS. COMMISSION

P. O. BOX 1930

HOBBS, NEW MEXICO 88240

0+5 - USGS - P.O. Box 1857  
Roswell, NM 88201

1 - Laura Richardson  
1 - Foreman EF 1 - File

Form 9-331  
Dec. 1973

Form Approved.  
Budget Bureau No. 42-R1424

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ gas ☐ other ☒ NIO well

2. NAME OF OPERATOR  
Getty Oil Company

3. ADDRESS OF OPERATOR  
P.O. Box 730 Hobbs, NM 88240

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)  
AT SURFACE: 660' FNL, 1652' FEL  
AT TOP PROD. INTERVAL:  
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐  
FRACTURE TREAT ☐  
SHOOT OR ACIDIZE ☐  
REPAIR WELL ☐  
PULL OR ALTER CASING ☐  
MULTIPLE COMPLETE ☐  
CHANGE ZONES ☐  
ABANDON\* ☐  
(other) Test casing

SUBSEQUENT REPORT OF:

☐  
☐  
☐  
☐  
☐  
☐  
☐  
☐

5. LEASE  
NM-02053

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

East Eumont Unit

8. FARM OR LEASE NAME

9. WELL NO.

13

10. FIELD OR WILDCAT NAME

Eumont

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 4, T19S, R37E

12. COUNTY OR PARISH 13. STATE

Ira

NM

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)

3703' DF

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

1. TIH w/4 1/2" packer.
2. Set packer at + 3800', pressure test annulus to 1000#.
3. If pressure does not hold, locate leak with RBP and pkr.
4. Squeeze leak w/class "C" cement.
5. TOH w/pkr. WOC.
6. Drill out cement.
7. Continue to test casing until all leaks are repaired.
8. TOH w/RBP and pkr.
9. Rig down well. Will remain TA.

RECEIVED

MAR 9 1983

Subsurface Safety Valve: Manu. and Type

18. I hereby certify that the foregoing is true and correct

SIGNED Dale R. Crockett

TITLE Area Superintendent

OIL & GAS  
MINERALS MGMT. SERVICE  
ROSWELL, NEW MEXICO

(Orig. Sgd.) PETER W. CHESTER

APPROVED BY  
CONDITIONS OF APPROVAL, IF ANY:

TITLE DATE

MAR 10 1983

FOR

JAMES A. GILLHAM  
DISTRICT SUPERVISOR

\*See instructions on Reverse Side

T.A. APPROVED FOR PERIOD  
ENDING MAR 10 1984

RECEIVED  
MAR 14 1983  
O.C.D.  
HOBBS OFFICE