

(SUBMIT IN TRIPLICATE)

Las Cruces  
J. S. Land Office  
034075-A  
Lease or permit No.

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Allottee

Lease No.

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	X
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Wink, Texas August 11, 1937

G.J. Saunders

Well No. 4 is located 1980 ft. from N line and 1980 ft. from W line of sec. 18

NE $\frac{1}{4}$  of SW $\frac{1}{4}$  of Sec. 18 19 S. 37 E. N.M.P.M.

( $\frac{1}{4}$  Sec. and Sec. No.)

(Twp.)

(Range)

(Meridian)

Monument

Lee

New Mexico

(Field)

(County or Subdivision)

(State or Territory)


The elevation of the derrick floor above sea level is 3708 ft.

### DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Set and cemented 3355' of 7"OD, 24#, 10thd., seamless casing (125 Jts.) at 3870' with 250 sacks of common cement. Completed cementing at 4:30 AM. 8-8-37.

Drilled plug at 11:00 PM. 8-10-37. Tested casing before and after drilling plug with 1300# pressure; tested OK.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company The Texas Company

Address Drawer K

Wink, Texas.

By

Title District Superintendent

