

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL <input type="checkbox"/> GAS <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Gulf Oil Corporation	8. From or Lease Name B. V. Culp (NCT-A)
3. Address of Operator P. O. Box 670, Hobbs, NM 88240	9. Well No. 3
4. Location of Well UNIT LETTER <u>F</u> <u>1980</u> FEET FROM THE <u>North</u> LINE AND <u>1980</u> FEET FROM THE <u>West</u> LINE, SECTION <u>19</u> TOWNSHIP <u>19S</u> RANGE <u>37E</u> NMPM.	10. Field and Pool, or Wildcat Eumont Gas Eunice Monument
15. Elevation (Show whether DF, RT, GR, etc.) 3698' GL	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <u>Attempted Plug Back</u> <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

POH with rods and pump. Cut off MA at 3722' (drop 3' of MA to bottom of hole). Pump Hydromite. Attempted to find plug back. RIH with pump and rods; pumping no gauge. Found flowline leaks, repaired flowline; pumping no gauge. Ran packer leakage test. Pumped 12 BO, 177 BW in 24 hrs. Pumped 4 BO, 216 BW before attempted plug back 3-29-82. Unable to plug back past old PBTD of 4007'.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED R. D. Pritch TITLE Area Engineer DATE 4-19-82APPROVED BY Orig. Signed by Les Clements TITLE Oil & Gas Insp. DATE APR 20 1982

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

APR 19 1982

U.S. HOUSE OF REPRESENTATIVES
HOUSE OFFICE