

NUMBER OF COPIES RECEIVED	
DISTRIBUTION	
TAXA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
TRANSPORTER	OIL
	GAS
PRODUCTION OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

FORM C-103
(Rev 3-55)

MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

Name of Company Daya Operating Company				Address 415 Citizens Nat'l Bank Bldg. Abilene, Texas			
Lease Atlantic-Terry	Well No. 1	Unit Letter M	Section 24	Township 19 S	Range 37 E		
Date Work Performed 8-22-61	Pool Wildcat			County Lea			

THIS IS A REPORT OF: (Check appropriate block)

- ☐ Beginning Drilling Operations
 ☐ Casing Test and Cement Job
 ☐ Other (Explain):
- ☒ Plugging
 ☐ Remedial Work

Detailed account of work done, nature and quantity of materials used, and results obtained.

Shot 4 1/2' casing off @ 2481'. Pulled and recovered 2481' of 4 1/2" casing. Ran tubing and spotted 20 sacks of regular neat cement from 2481-2387'. Spotted 20 sacks of regular neat cement from 300' - 240'. Placed 10 sacks of regular neat cement in top of 8 5/8" O.D. casing. Hole was filled and circulated with heavy mud prior to shooting off 4 1/2" casing. The location has been leveled and a regulation marker installed.

Witnessed by **Bubba Spears**
 Position **Agent**
 Company **Daya Operating Company**

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

ORIGINAL WELL DATA

D F Elev.	T D	P B T D	Producing Interval	Completion Date
Tubing Diameter	Tubing Depth	Oil String Diameter	Oil String Depth	
Perforated Interval(s)				
Open Hole Interval		Producing Formation(s)		

RESULTS OF WORKOVER

Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPD	GOR Cubic feet/Bbl	Gas Well Potential MCFPD
Before Workover						
After Workover						

OIL CONSERVATION COMMISSION

I hereby certify that the information given above is true and complete to the best of my knowledge.

Approved by <i>[Signature]</i>	Name <i>[Signature]</i>
Title	Position Superintendent
Date	Company Daya Operating Company