NEW MEXICO OIL CONSERVATION COMMISSION Santa Fe, New Mexico

MISCELLANEOUS REPORTS ON WELLS

Submit this report in TRIPLICATE to the District Office, Oil Conservation Commission, within 10 days after the work specified is completed. It should be signed and filed as a report on Beginning Drilling Operations, Results of test of casing shut-off, result of plugging of well, result of well repair, and other important operations, even though the work was witnessed by an agent of the Commission. See additional

	Indicate Nature of Report by Checking Be	low	
REPORT ON BEGINNING DRILLING OPERATIONS	REPORT ON RESULT OF TEST OF CASING SHUT-OFF	REPORT ON REPAIRING WELL	x
REPORT ON RESULT OF PLUGGING WELL	REPORT ON RECOMPLETION OPERATION	REPORT ON (Other) FUMP INSTALLATION	x
	July 19, 1954	Hobbs, New Mexic	
Following is a report on the work done	and the results obtained under the heading	(Place	,
The Chic Cil Company	Powi	cha Barber	
(Company or Operator)	, Well No.	(Lease)	5
20S , R 37E , NMPM , Monu	ment Pool.	Lea	Count
he Dates of this work were as folows:			
	submitted on Form C-102 on	(Cross out incorrect words)	, 197.
DETAILED A ctal Depth 3895; PBTD 3787. Smented 3895 to 3825; ran tub mabbed 150 bbls. water with the sax cement and found top of cil. Continued to swab, oil lowing and died. Resumed swa	AN) obtained. ACCOUNT OF WORK DONE AND RESU Pulled tubing 3-29-54; swall ing; circulated and lost mid; race of oil. Plugged back to ud and pulled tubing. Tagged plug at 3787 ck. Reran tub 1 increasing to 35% and water bbing; then installed rods ar	trs obtained for packer pulled tubing; reran to 3795; swabbed 300 bbls top of plug at 3795; doing 4-28-54. Swabbed 95 decreasing to 65%; well	r rubb bing. . flui hmped % wate
DETAILED A otal Depth 3895; PBTD 3787. emented 3895 to 3825; ran tub wabbed 150 bbls. water with t 8% water; displaced water w/m 2 sax cement and found top of 3 oil. Continued to swab, oil towing and died. Resumed swand 200 bbls water, 6-25-54.	Pulled tubing 3-29-54; swaling; circulated and lost mud; race of oil. Plugged back to ud and pulled tubing. Tagged plug at 3787 ck. Reran tubling then installed rods ar GOR 443:1.	obed and fished for packed pulled tubing; reran tube 3795; swabbed 300 bbls top of plug at 3795; doing 4-28-54. Swabbed 95 decreasing to 65%; welled pump. Pumped 185 bbls	r rubbe bing. . fluid hmped % water
DETAILED A otal Depth 3895'; PBTD 3787'. mented 3895 to 3825; ran tub mabbed 150 bbls. water with t swater; displaced water w/m sax cement and found top of toil. Continued to swab, oi lowing and died. Resumed swa and 200 bbls water, 6-25-54.	AN) obtained. ACCOUNT OF WORK DONE AND RESU Pulled tubing 3-29-54; swall ing; circulated and lost mid; race of oil. Plugged back to ud and pulled tubing. Tagged plug at 3787 ck. Reran tub 1 increasing to 35% and water bbing; then installed rods ar	obed and fished for packed pulled tubing; reran tube 3795; swabbed 300 bbls top of plug at 3795; doing 4-28-54. Swabbed 95 decreasing to 65%; welled pump. Pumped 185 bbls	r rubbe bing. . fluid hmped % water

(Date)

(Title)

Address. Box. 2107. Hobbs. New Mexico