



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Budget Bureau No. 42-R358.4.
For n Approved,

Land Office Las Cruces

Lease No. 031621 (S)

Unit Bitter B

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....		SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....		SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....		SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....		SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....			
<u>Repair Casing Leak</u>	X		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

November 29, 1962

Well No. 2 is located 330 ft. from N line and 1650 ft. from E line of sec. 5

4, T. 4, Sec. 5 20-S 37- N.M.P.M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)

Monument-Pad lock Lee New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3545 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Found holes in casing between 2635 and 2643'. Cut off 5-1/2" casing at 2665'. Pulled casing and replaced 240'. Ran casing with Beach Boss casing bowl. Pressured casing to 1200# for 10 minutes. No decrease in pressure.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Union Texas Petroleum Corporation

Address P.O. Box 196

Midland, Texas

By Charles E. Spence
Title District Clerk