

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

N.M. ON 100
P.O. BOX 100
Hobbs, NM 88401
RECEIVED
MAY 21 1999

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.

Use "APPLICATION FOR PERMIT -" for such proposals.

SUBMIT IN TRIPLICATE

1. Type of Well
☒ Oil Well ☐ Gas Well ☒ Other

2. Name of Operator
Amerada Hess Corporation

3. Address and Telephone No.

P.O. Box 840, Seminole, TX 79360

915 758-6700

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1830' FWL, 2130' FSL, Sec. 6, T20S, R37E.

5. Lease Designation and Serial No.

LC-031621-A

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Britt "A"

3

9. API Well No.

30-025-05968

10. Field and Pool, or exploratory Area

Eunice Monument G/SA

11. County or Parish, State

Lea

N.M.

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent

☒ Subsequent Report

☐ Final Abandonment Notice

TYPE OF ACTION

☐ Abandonment

☐ Recompletion

☐ Plugging Back

☐ Casing Repair

☐ Altering Casing

☒ Other TA'd well.

☐ Change of Plans

☐ New Construction

☐ Non-Routine Fracturing

☐ Water Shut-Off

☐ Conversion to Injection

☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work)*

5-17 thru 5-19-99

MIRU Tyler Well Svc. pulling unit & TOH w/rods & pump. Removed wellhead, installed BOP & TOH w/tbg. TIH w/CIBP set at 3328'. Press. tested CIBP to 500#. Held OK. Removed BOP & installed wellhead w/1 jt. 2-3/8" tbg. in tbg. hanger. RDPU & cleaned location. Circ. pkr. fluid. Press. tested csg. to 540 PSI for 30 min. Held OK, chart attached. Well status changed to TA'd.

Amerada Hess Corporation respectfully request a TA'd status on well until such time as it is economically feasible to re-enter wellbore.

APPROVED FOR 12 MONTH PERIOD
ENDING MAY 19 2000

14. I hereby certify that the foregoing is true and correct

Signed

Title Sr. Petroleum Engineer

Date 5-20-99

(This space for Federal or State office use)

Approved by (ORIG. SGD.) DAVID R. GLASS

Title PETROLEUM ENGINEER

Date MAY 28 1999

Conditions of approval, if any:

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

* See Instruction on Reverse Side

GW

mt

