

FIELD <i>Monument (Blinebry)</i>	OPERATOR <i>Union Texas Petr.</i>	DATE <i>4-29-76</i>
LEASE <i>Britt</i>	WELL NO <i>11</i>	LOCATION <i>1650' FNL & 1650' FEL Sec. 7, T-20-S, R-37-E, Lea County, New Mexico</i>

T/A June '66

13 3/8 @ 612' w/450 sx (Cont. Cir.)

Top Cmt. @ 684' (Temp. Surv.)

Cut 5 1/2" Csg. @ 3100' (4-13-61) Reran Csg. & replaced bad joint.

8 5/8" casing set at 3298' with 1900 sx of _____ cement
Hole size *11* "

Csg. Leak @ 3370', Sg. w/200 sx (Dr'd. out to 5660')

Top Cmt. @ 3645'

2 3/8" EVE Tbg. @ 5642'

Perf. 5540-42' (8 shots in error)

Tbg. Anchor @ 5576'

Perf. 5640-90' w/4 holes/ft. } - Blinebry (Sg. Jan. '66 w/75 sx.)
Re-Perf. 5640-60 w/4 holes/ft. }
Perf. 5642'-48' w/4 holes/ft. - Blinebry

5 1/2" casing set at 5705' with 500 sx of 300 sx 4 7/8" 3000 lb. cement
Total Depth *5710'* Hole size *7 7/8"*