



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office **Las Cruces**

Lease No. **LC 031621 (a)**

Unit **H. M. Brist**

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	Subsequent Report of Plug Back to San Andres

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

July 25, 19**63**

Well No. **13** is located **2310** ft. from **XX** line and **1650** ft. from **E** line of sec. **7**
SW/4, SE/4 Sec. 7 **20-S** **37-E** **N.M.P.M.**
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Monument Gray. San And. **Lea County** **New Mexico**
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is **3562** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Pulled tubing with packer. Ran Lane Wells GRN log 3400-3913'. Squeezed Perfs. 5190-5210'. Perforated 3688-3694' with 2 holes per ft. Acidized with 2000 gals. Well flowed 71.63 bbls oil and 405.37 bbls water in 24 hrs. on 32/64" choke, GOR 6422.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Union Texas Petroleum Corporation**

Address **Box 1859**

Midland, Texas

By

Title **District Clerk**