NUMBER OF CO	PIES RECEIVED							
SANTA FF FILE		NI	W MEXICO O	IL CONSER	NOITAY	COMMISSION	FORM C-103	
U.S.G.S. LANDOFFICE TRANSPORTER OIL TRANSPORTER OIL MISCELLANEOUS REPORTS ON WELLS								
PRORATION OF OPERATOR	FICE	(Submit	to appropriate l	District Office	as per Com	mission Rule 1	106)	
Name of Com				Address			· · · · · · · · · · · · · · · · · · ·	
Culf Oi Lease	l Corporati		ell No. Unit	Letter Section		Hew Hexico	lange	
Bertie	ihitmire			P 8	20-8		37-E	
Date Work P.		Pool Morane	mt Blinebry		County Log			
			A REPORT OF:					
Beginni	ng Drilling Oper		ing Test and Cem	ent Job	Other (E	Explain):		
Plugging Remedial Work Clean cut and acidise Detailed account of work done, nature and quantity of materials used, and results obtained.								
packer Acid.	at 5611.	of tail pipe. Acidised 7º earsure 1800#, min. Inserted Baker Fi	sing perfora 500# to vac 8 pecker. H	tions 5650 mm in 3 m	1 ~ 5685° An. IR 3 d pump.	with 500 g bpm. Flus	als 15% NE hed with 22	
Witnessed by Position J. H. Noss Produ						ompany Gulf Oil Corporation		
		FILL IN BEL	OW FOR REME!		EPORTS OF	NLY		
D F Elev. TD PBTD				Producing Interval Completion Date				
35631		5700	5696			- 5685 Oil String	9-17-53	
2-3/8"		Tubing Depth 5694	Oil String Diam		eter	56 9 9		
Perforated In								
Open Hole Interval				Producing Formation(s) Idne				
			RESULTS OF	WORKOVER				
Test	Date of Test	Oil Production BPD	Gas Produc MCFPI		Production BPD	GOR Cubic feet/Bb	Gas Well Potential MCFPD	
Before Workover	12-19-61	6			0	••	-	
After Workover	2-7-62	2h			0		renes.	
	OIL CONSE	RVATION COMMISSION			ify that the in f my knowled		above is true and complete	
Approved by	11	2,		Name	The !	Lexace		
Title:	<u> </u>			Position	duction !	langear		
Date				Company	orpore			