VERTILOG®



CUSTOMER	ARCO OIL & GAS COMPAI	NY			DATE 6-5-79
WELL	BERTHA J. BARBER #16			SERVICE ORDER NO.	33599
FIELD	MONUMENT PADDOCK	COUNTY	LEA	STATE	NEW MEXICO
CASING SIZE	7" WEIGHT(S) 23#	GRADE J-5	5	NOMINAL WALL THICKNESS	
TOTAL FOOT	AGE INSPECTED 5170	FROM	5170'	TO SURI	

SUBSURFACE CASING INSPECTION REPORT						
	SUMMARY					
33	LENGTHS WERE FOUND TO SHOW NO EVIDENCE OF CORROSION EXCEEDING PERCENT OF THE NOMINAL BODY WALL.	20 CLASS 1				
16	LENGTHS WERE FOUND TO SHOW EVIDENCE OF CORROSION EXCEEDING PERCENT BUT LESS THAN 41 PERCENT OF THE NOMINAL BODY WALL.	20				
	LENGTHS WERE FOUND TO SHOW EVIDENCE OF CORROSION EXCEEDING PERCENT BUT LESS THAN 61 PERCENT OF THE NOMINAL BODY WALL.	40 CLASS 3				
	LENGTHS WERE FOUND TO SHOW EVIDENCE OF CORROSION EXCEEDING _PERCENT OF THE NOMINAL BODY WALL. TOTAL LENGTHS	60 CLASS 4				
<u>5170'</u>	TOTAL FOOTAGE					
REFERENCE FOR FOOTAGE MEASURE						
LENGTHS ARE NUMBERED FROM						
COMMENTS **THE TWO BOTTOM LENGTHS CONTAIN KNOWN PERFORATIONS AND SHOULD						
BE INCLUDED IN THE ABOVE TOTAL.						
LENGTHS MARKED "CLASS 4-SEE REPORT" SHOW INDICATION OF						
POSSIBLE COMPLETE PENETRATION OF THE NOMINAL BODY WALL.						
THE HOMINAL BODY WALL.						
	7					
SERVICED BY BILL GRAHAM .						