STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMEN		
CIST HINUTION	OIL CONSERVATION DIVISION	
SANTA PT	P. O. DOX 2038	Farm C-103
FILE	SANTA FE, NEW MEXICO 87501	Sevised 10-1-
U.S.G.S.		Sur indicate Type of Louise
LAND OFFICE		
OPERATOR		
		S. State Dil & Gus Leann No.
SUNDRY 100 NOT USE THIS POON FOR FOR	NOTICES AND REPORTS ON WELLS	
014 X 645		7. Unit Agreement Heate
2. Aname ul Operulor	07HER.	i cane
· Amoco Production Company		U. Farm or Lease lourse
J. Aduress of Chergion		
P. O. Box 68, Hobbs, New	Maxica 88240	South Hobbs (GSA) Unit
4. Location of well	mex1c0 88240	
		10. Field and Pool, or Amucat
UNIT LETTER B 66	North 2370	
En et	•	Hobbs (GSA)
THEEast	3 19-S 38-E	//////////////////////////////////////
THE	NM	••• ())))))))))))))))))))))))))))))))))
	15. Elevation (Show whether DF, RT, CR, etc.)	<u> </u>
	3617' RDB	Lea
Check Ar	DECERTIZIO BOX T- 1-11	
NOTICE OF INT	propriate Box To Indicate Nature of Notice, Report or (	Other Data
•	SUBSEQUE	NT REPORT OF:
PERTORN REMEDIAL WORK		
	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
PUL ON ALTEN CASING	COMMENCE DRILLING OPHS.	PLUG AND ABANGONMENT
	CHANGE PLANS CASING TEST AND CEMENT JOB	LOG AND ABANGONMENT
5 THE #	OTHER	<b></b>
	L	
17. Descrite Processi or Completed Opere	allens (Clearly state all and	•
LICIA) SEE RULE 1103.	ations (Clearly state ail pertinent details, and give pertinent dates, include	ng estimated date of starting any proposed
HOVED AN SELVICE UNIT 5-11	1-83. Ran pump in trace survey and charad and	

Moved in service unit 5-11-83. Ran pump in trace survey and showed squeezed zone I perfs taking 68% fluid level. Cleaned out fill to 4190'. Cement retainer set at 3937'. Squeezed with 100 sacks class C cement, 100 sacks class C cement with 5#/sack tuf plug and circulated out 65 sacks class C cement and 18% NACL. Reversed out 6 sacks cement. Drilled out to 2249' and pressure tested to 1000 psi and 0K. Drilled out to 4190' and pressure tested to 1000 psi . Bled to 300 psi and casing leaking. Retrievable bridge plug set at 2626' and packer set at 1987'. Squeezed with 425 sacks class C cement and 18% NACL. Circulated out 12 sacks cement. Drilled out to 240' and pressure down to 200 psi and 0K. Drilled out to 2187 and pressure tested to 600 psi and 0K. Drilled out to 2187 and pressure tested to 600 psi and 0K. Drilled out to 2187 and pressure tested to 600 psi and 0K. Drilled out to 2187 and pressure tested to 600 psi and 0K. Drilled out to 2187 and pressure tested to 600 psi and 0K. Drilled out to 2187 and pressure tested to 600 psi and 2310'. Pumped 50 sacks class C cement, 50 sacks Thix-set cement and 200 sacks class C cement tested to 600 psi and 0K. Aborted additional efforts for repair casing and cleaned out to 4224'. Ran mother hubbard and landed at 4158'. Ran seating nipple and landed at 4133'. Nipple down and pump stuck. Bump pump valves and restart. Pumped 7 B0, 206 BW, and 0 MCF in 264 hours. Last 24 hours pumped 0 B0, 4 BW, and 0 MCF. Returned to production.

ORIGINAL SIGNED BY JERRY SEXTON DISTRICT I SUPPRIVISOR	717LE	AUG 1 6 1983
men Fulu Joina	Assist. Admin. Analyst	8-9-83
1. Pietra Lewi Shet the information appre is true and complet	e to the best of my knowledge and belief.	
0+4-NMOCD,H 1-HOU R. E. Ogden RM 21.15	0 1-F. J. Nash, HOU RM 4.206 1-SU	SP 1-PJS

