

SCHLUMDER(WELL SERVICES 5000 GULF FREEWAY, P.O. BOX 2175 HOUSTON, TEXAS 77001, (713) 928-2511

May 11, 1978

PLEASE REPLY TO BOX 1090 HOBBC, NEW MEXICO 60240



Amoco Production Company Drawer A Levelland, Texas 79336 Attn: Mr. Ed Staley

RE: CBL-VDL - South Hobbs #38

Dear Mr. Staley:

A Cement Bond-Variable Density Log was recorded in your South Hobbs Unit #38 well in Lea County on May 6, 1978. The log was recorded inside 5½" casing from 4103' to 2930'.

The following interpretation was made from this log:

INTERVAL	INTERPRETATION	REASON
4103' 3165'	Excellent Bond	Transit Time Curve indicated strong for- mation arrivals (sup- ported by VDL) - low amplitude readings.
3166' - 2930'	Poor or No Bond	High amplitude readings and strong casing arrivals on the VDL

3148'

Estimated TOC

If you have any questions concerning this log or the interpretation please call us. Thank you for using Schlumberger.

C. R. McMath District Manager

RCB/mp