NEW MEXICO OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

MISCELLANEOUS REPORTS ON

Submit this report in TRIPLICATE to the District Office, Oil Conservation Commission, within 10 pleted. It should be signed and filed as a report on Beginning Drilling Operations, Results of test of casing shut-off result of well repair, and other important operations, even though the work was witnessed by an agent instructions in the Rules and Regulations of the Commission.

Indicate	Nature o	ď	Report by	y	Checking	Below
----------	----------	---	-----------	---	----------	-------

REPORT ON BEGINNING DRILLING OPERATIONS	REPORT ON RESULT OF TEST OF CASING SHUT-OFF	REPORT ON REPAIRING WELL		
REPORT ON RESULT OF PLUGGING WELL	REPORT ON RECOMPLETION OPERATION	REPORT ON Tests Re-		

September 28, 1953 Hobbs, New Mexico

Following is a report on the work done and the results obtained under the heading noted above at the

Stanolind Oil and	Gas Company		E. H.	Byers	NW/3	•••••	
(Company or Op	erator)			(Lease)			
(Contractor)	, Well No	in the.	74		01 Stc	
T. 195, R 38E , NMPM,	Hobbs	Pool,	••••	Lea		Cour	ity
The Dates of this work were as folows:	September 3	1953	•••••				
Notice of intention to do the work () (was not) submitted on Fe	orm C-102 on	(Cross out	incorrect wo	rds)	, 19	
and approval of the proposed plan (was) (was not) obtained.						

DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED

Tubing pressure 545 psig

Casing pressure zero psig

No leaks indicated by attached temperature survey.

Repairing of old oil string, running of new oil string and zero casing pressure preclude possibility of leaks.

No additional work planned.

Rowl	and Laxson	Stanolind	Oil and	Gas	Roustabou	t
Witnessed by	(Name)		(Company)	***************************************	(Title)	
Approved OIL CO	esservation commis	SSION	I hereby cer to the best	tify that the intoff my knowledge	formation given above is ge.	true and complete
\	(Name)		Position	Field	Engineer	
0				, Stanol	ind Oil and G	las
			Address	Box 68		Mexico
(Title)		(Date)	Audicas			

