

DUPLICATE

OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

MISCELLANEOUS REPORTS ON WELLS

RECEIVED
FEB 15 1950
OFFICE

Submit this report in triplicate to the Oil Conservation Commission or its proper agent within ten days after the work specified is completed. It should be signed and sworn to before a notary public for reports on beginning drilling operations, results of shooting well, results of test of casing shut off, result of plugging of well, and other important operations, even though the work was witnessed by an agent of the Commission. Reports on minor operations need not be signed and sworn to before a notary public. See additional instructions in the Rules and Regulations of the Commission.

Indicate nature of report by checking below.

REPORT ON BEGINNING DRILLING OPERATIONS		REPORT ON REPAIRING WELL	
REPORT ON RESULT OF SHOOTING OR CHEMICAL TREATMENT OF WELL		REPORT ON PULLING OR OTHERWISE ALTERING CASING	
REPORT ON RESULT OF TEST OF CASING SHUT-OFF		REPORT ON DEEPENING WELL	
REPORT ON RESULT OF PLUGGING OF WELL	X		

February 14, 1950 Hobbs, New Mexico

Date

Place

OIL CONSERVATION COMMISSION,
SANTA FE, NEW MEXICO
Gentlemen:

Following is a report on the work done and the results obtained under the heading noted above at the _____

Stanolind Oil and Gas Company Will Terry Well No. **1** in the _____

Company or Operator

Lease

SW/4 of Sec. **26**, T. **19-S**, R. **38-E**, N. M. P. M.,

Wildcat Field, **Lea** County.

The dates of this work were as follows: **February 3, 1950 to February 10, 1950**

Notice of intention to do the work was (~~was not~~) submitted on Form C-102 on **February 2** 19 **50**

and approval of the proposed plan was (~~was not~~) obtained. (Cross out incorrect words.)

DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED

Inasmuch as no casing could be recovered, the following cement plugs were placed in order to isolate all indicated fluid bearing zones: with heavy mud laden fluid left between cement plugs.

50 sacks

9670 - 9550'

25 sacks

7800 - 7900

50 sacks

7100 - 7000

(over)

24 sacks

5100 - 5000

Witnessed by **T. S. Holden** **Stanolind Oil and Gas Co. Head Rsbt.**

Name

Company

Title

Subscribed and sworn before me this **14th**

day of **February** 19 **50**

[Signature]

Notary Public

I hereby swear or affirm that the information given above is true and correct.

Name **Ralph Henderson**

Position **Field Superintendent**

Representing **Stanolind Oil and Gas Company**
Company or Operator

My commission expires **2-23-50**

Address **Box "F", Hobbs, New Mexico**

Remarks:

[Signature]

Name

Oil & Gas Inspector

Title

APPROVED

FEB 15 1950

30 sacks
15 sacks

3521 - 3421'
60 - Surface

A 4" permanent marker extending 5 feet above the ground level was erected at the surface.