Submit 3 Copies to Appropriate

CONDITIONS OF APPROVAL, IF ANY:

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

| District Office | - | | | | |
|--|---|---|--|--|---|
| DISTRICT I P.O. Box 1980, Hobbs NM 88241-1980 | OIL CONSERVATI | | WELL API NO. | | |
| P.O. Box 1980, Hobbs NM 88241-1980 P.O. Box 2088 DISTRICT II Santa Fe, New Mexico 87504-2088 | | 30-025-08715 | | | |
| P.O. Drawer DD, Artesia, NM 88210 | | | 5. Indicate Type | of Lease STATE [| X FEE |
| DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410 | | | 6. State Oil & C | | |
| SUNDRY NOTICES AND REPORTS ON WELLS | | | | | |
| | POSALS TO DRILL OR TO DEEPE VOIR. USE "APPLICATION FOR F 101) FOR SUCH PROPOSALS.) | | 7. Lease Name | or Unit Agreeme | nt Name |
| I. Type of Well: OIL GAS WELL GAS WELL X | OTHER | | Н. Т. ORCUT | T (NCT-D) | |
| 2. Name of Operator | | | 8. Well No. | | |
| Chevron U.S.A. Inc. | | | 2 | W/14 | |
| 3. Address of Operator P.O. Box 1150, Midland | . TX 79702 | | 9. Pool name or EUMONT: YATE | | EEN(PRO GAS) |
| 4. Well Location Unit Letter G: 1980 | | Line and 19 | | | EAST Line |
| Section 13 | Township 20S | Range 36E ether DF, RKB, RT, GR, etc 3353' | NMPM c.) | LEA | County |
| 11. Check Ani | oropriate Box to Indicat | | Report or | Other Data | <i></i> |
| NOTICE OF IN | • • | 1 | SEQUENT | | |
| | | | | | |
| PERFORM REMEDIAL WORK | PLUG AND ABANDON | REMEDIAL WORK | X | ALTERING CA | asing L |
| TEMPORARILY ABANDON L CHANGE PLANS L COMMENCE DRILLING | | | OPNS. | PLUG AND A | BANDONMENT L |
| PULL OR ALTER CASING CASING TEST AND CE | | | MENT JOB | | |
| OTHER: | | OTHER: | | | [|
| 12. Describe Proposed or Completed Operwork) SEE RULE 1103. | ations (Clearly state all pertinent | letails, and give pertinent da | tes, including estin | iated date of sta | rting any proposed |
| SX IN FORM. PERFD 4 PRESS 500#. PERFD 4 "C" @ 2512'; BRK CIF @ 3309'. RAN CBL/GF HOLES). FRAC W/500 2477'-2835' (26 HOLE CLEAN OUT TO 2902'. | JMPED 100 SX "C" CMT @ 3: \$ SQZ HOLES @ 2570'; PRE: \$ SQZ HOLES @ 1500'; BRO! RC & CMT 5-1/2 X 7-7/8 2! R/CCL 2700'-1500'; LOG IN GALS 7-1/2% ACID, 20,000 ES). TEST RBP 1000#. FR SWABBED. PU & SET RBP CIRC HOLE CLEAN, TEST 75 | SS ATTEMPTED TO BREA KE CIRC THRU SQZ PER 570'-1500'. TAG CMT NDICATES GOOD CMT. O GALS 50Q GEL. SET RAC W/62,000 GAL 50Q @ 3210'. PUMP 100 | K CIRC UP 5- FS & CIRC CLE @ 2485', DO PERFD 2939'-(RBP @ 2909'; GEL, 228,000 SX "C" @ 1500 | 1/2 X 7-5/8 EAN. PUMP 1 CMT TO 2577 3192' W/2 JH TST 500#. D# 12/20 SAN D; TAG @ 141 | ANN; 125 SX 7'; TAG HPF (26 PERF ND. 18', |
| WORK PERFORMED 6/16/ | 96 - 7/27/96. | | | | |
| | | | | | |
| I hereby certify that the information above is tru | e and complete to the best of my knowle | dge and belief. | | | |
| SIGNATURE J. K. | 1 | TILE REGULATORY T.A. | | DATE | 8/12/96 |
| TYPE OR PRINT NAME J. K. RIPLEY | | | | TELEPHONE NO. | (915)687-7148 |
| (This space for State Use) | STATES CANCED | | | Aui | G 15 1995 |
| APPROVED BY | 1 | TILE | | DATE | |

