

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-12728
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	A-1543-1
7. Lease Name or Unit Agreement Name	
NORTH MONUMENT G/SA	
BLOCK 4	
8. Well No.	15
9. Pool name or Wildcat	EUNICE MONUMENT G/SA

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:	OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator	AMERADA HESS CORPORATION
3. Address of Operator	DRAWER D, MONUMENT, NM 88265
4. Well Location	Unit Letter 0 : 660 Feet From The SOUTH Line and 1980 Feet From The EAST Line

Section 24	Township 19S	Range 36E	NMPM	LEA	County
10. Elevation (Show whether DF, RKB, RT, GR, etc.)					

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: TESTED CASING <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5-13-93 THRU 5-19-93

MIRU RAM WELL SER. PULLING UNIT AND TOH W/RODS & PUMP. REMOVED WELLHEAD, INSTALLED BOP & TOH W/TUBING. TIH WITH 4-3/4" BIT. TAGGED FILL IN OPEN HOLE AT 4,007' (21' OF FILL) & TOH. TIH WITH 5-1/2" X 2-3/8" ELDER RBP. SET AT 3,800'. PRESS. CASING W/520 PSI. ATTEMPTED TO PERFORM CASING INTEGRITY TEST, COULD NOT PRESSURE DUE TO WELLHEAD FLANGE LEAKING. TIGHTENED FLANGE & ATTEMPTED TO PRESSURE TEST PRODUCTION CASING AND THE RESULTS WERE THE SAME WITH WELLHEAD LEAKING. THREADS ON HINDERLITER WELLHEAD WERE SEVERELY CORRODED AND PITTED. UNABLE TO HOLD PRESS. RIGGED DOWN PULLING UNIT. DUG OUT CELLAR AND INSTALLED CELLAR KIT. K&S PAINTING SANDBLASTED OLD WELLHEAD. RAM WELL SER. RIGGED UP PULLING UNIT. LOADED CASING W/FRESH WATER & DUMPED 3 SKS. SAND ON RBP AT 3,800'. CUT OF 9-5/8" HINDERLITER CASING-HEAD. TIH W/CASING SPEAR, REMOVED SLIPS, STACKED OUT 5-1/2" CASING, WELDED ON CASING COLLARS & CHANGED OUT WELLHEAD. INSTALLED A NEW NATIONAL 11" 3M X 9-5/8" CASINGHEAD AND A 7-1/16"

I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNATURE	TITLE	DATE
ROY L. WHEELER, JR.	SUPV. ADMIN. SER.	6-24-93
TYPE OR PRINT NAME		TELEPHONE NO. 393-2144

(This space for State Use)	Orig. Signed by Paul Kautz Geologist	APPROVED BY	TITLE	DATE
				JUN 28 1993
CONDITIONS OF APPROVAL, IF ANY:				

**RECEIVED**

JUN 25 1993

JO HOBBS  
OFFICE