

NEW MEXICO OIL CONSERVATION COMMISSION
MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106).

COMPANY Pan American Petroleum Corporation Box 68 Hobbs, New Mexico
(Address)

LEASE W.M. Terry Tract 2 WELL NO. 13 UNIT K S 10 T 19 R 38

DATE WORK PERFORMED November 1957 POOL Hobbs

This is a Report of: (Check appropriate block) ☐ Results of Test of Casing Shut-off
☐ Beginning Drilling Operations ☐ Remedial Work
☐ Plugging ☒ Other Preparation of casing for leak inspection

Detailed account of work done, nature and quantity of materials used and results obtained.

In accordance with NMOCC Memorandum No. 33-57 dated 11-18-57 the following work was performed on subject well. Approximately 60' of 1" tubing was run below top of open surface casing. A bridge was placed above the bottom of 1" pipe and casing was filled with cement to surface. A valve was placed on 1" pipe and left in an open position above ground level.

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

Original Well Data:

DF Elev. _____ TD _____ PBD _____ Prod. Int. _____ Compl Date _____
Tbng. Dia _____ Tbng Depth _____ Oil String Dia _____ Oil String Depth _____
Perf Interval (s) _____
Open Hole Interval _____ Producing Formation (s) _____

RESULTS OF WORKOVER:

	BEFORE	AFTER
Date of Test	_____	_____
Oil Production, bbls. per day	_____	_____
Gas Production, Mcf per day	_____	_____
Water Production, bbls. per day	_____	_____
Gas-Oil Ratio, cu. ft. per bbl.	_____	_____
Gas Well Potential, Mcf per day	_____	_____
Witnessed by _____		
	(Company)	

OIL CONSERVATION COMMISSION

Name _____
Title _____
Date _____

I hereby certify that the information given above is true and complete to the best of my knowledge.

Name Ralph W. Henderson
Position Field Superintendent
Company Pan American Petroleum Corporation