

MAKATHUNOIL COMPANY
LEA UNIT NO. 3
LEA PENNGAS - LEA DEV. CIL
ANNUAL PACKER LEAKAGE TEST
LEA COUNTY NEW MEXICO
8-20 TO 8-21-72

DWG @ 9:00 AM 8-21-72
PENNY 10
DEV 886

ARC-20 RECORDING CHART
80-1000-12

American Electric Chart Co.

ARC-20 CHARTS
MADE IN
LOS ANGELES, CALIF.