

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYLand Office Las CrucesLease No. LC-071900-AUnit Federal Land 6015 ANG

RECEIVED

AUG 8 1963

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Hotchkiss, New Mexico, August 2, 1963Well No. 2 is located 336 ft. from N line and 1900 ft. from W line of sec. 934 1/4 (Sec. and Sub. No.) 20 (Twp.) 11E (Range) 12N (Meridian)
West (Field) 1-00 (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spudded 12:00 Noon July 30, 1963 - 12 1/4" hole.

TD 1285 Ft. Anhydrite- Set 9 5/8" OD 32# H40 R2 SS BHT Casing @ 1285 Ft. with 450 Sks. Reg. Cement plus 4% Gel & 2% Calcium Chloride & 4 Lb. Flu-seal per sack, Cement Circulated (20 Sks. out) Completed 9:00 AM August 1, 1963 (4- Larkin Cement-raisers on bottom & Jts.)

Tested 9 5/8" OD Casing with 1000# pump pressure for 30 Min. before and after drilling cement- No decrease in pressure.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Sinclair Oil & Gas CompanyAddress 520 E. Broadway, Hobbs, N.M.

By _____

Title Dist. Supt.