


(SUBMIT IN TRIPLICATE)

Land Office **New Mexico**Lease No. **NM0250**Unit **A**UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	<b>X</b>
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

**Hobbs, N. Mex. Mar. 7**, 19 **63**Well No. **2** is located **330** ft. from **N** line and **660** ft. from **E** line of sec. **1****NE/4NE/4 1**  
(1/4 Sec. and Sec. No.)**20a**  
(Twp.)**34a**  
(Range)**NMPM**  
(Meridian)**Undesignated**  
(Field)**Lea**  
(County or Subdivision)**New Mexico**  
(State or Territory)The elevation of the derrick floor above sea level is **3698** ft.

## DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Lease designated as **Texaco Federal**.

Drilled 7-7/8" hole to depth of 5000' and ran 158 jts 4-1/2" casing landed at T.D. and cemented w/200 sack cement 50-50 inner & neat. Circulated casing on bottom. Waited on cement 24 hours. Pressured up on casing to 1000# logging no drop in pressure for 1 hour. proceeded with work phases toward completion of well.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Cactus Drilling Company**Address **Box 1826, Hobbs, New Mex.**

By

Title **Vice-President**