



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office _____

Lease No. **LC-066126**

Unit **23 AM '63**

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Hanson "C"

September 23, 1963

Well No. **3** is located **330** ft. from **SW** line and **1650** ft. from **SE** line of sec. **23**

SE/4 SW/4 Sec. 23
(1/4 Sec. and Sec. No.)

20 S
(Twp.)

34 E
(Range)

NMPM
(Meridian)

Undesignated (Lynch)
(Field)

Lea
(County or Subdivision)

New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spudded 9/15/63. Cemented 8 5/8" 28# casing at 245 feet with 175 sacks. Cement circulated. Plug down 5:30 P.M. 9/15/63. WOC 24 hours and pressure tested casing with 600# for 30 minutes, test O.K.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Bark Royalty Company**

Address **c/o Oil Reports & Gas Services**

Box 763

Hobbs, New Mexico

By

A. L. Smith

Title **Agent**