



(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office **Hobbs, New Mexico**

Lease No. **LC-065649-B**

Unit \_\_\_\_\_

JAN 11 AM 8 27

**SUNDRY NOTICES AND REPORTS ON WELLS**

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	<b>XX</b>
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

January 11, 1963

Well No. 1 is located 1980 ft. from N line and 660 ft. from E line of sec. 17

NE 17 20 S 35 E  
( $\frac{1}{4}$  Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
Wildcat Lea New Mexico  
(Field) (County or Subdivision) (State or Territory)

The elevation of the ground floor above sea level is 3699.7 ft.

**DETAILS OF WORK**

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spudded 12:30 pm 12/26/62. Drilled 17 $\frac{1}{2}$ " hole to 898'.  
Set  $\frac{3}{8}$ " 61# J55 R-2 New at 894'.  
Cemented with 365 sx Incoer + 4% gel & 200 sx Incoer neat.  
Plug down at 1:00 pm 12/28/62. Circulated cement to surface.  
Waited on cement 24 hrs. Pressured up on casing with 100 psi. No pressure drop in one hour.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company JAKE L. HAMON

Address 500 Vaughn Building

Dallas 1, Texas

By [Signature]

Title Chief Production Clerk