

NUMBER OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
TRANSPORTER	OIL
	GAS
PRODUCTION OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

FORM C-103
(Rev 3-55)

MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

Name of Company Martin Yates, III		Address 323 Carper Bldg., Artesia, N. Mex.	
Lease Bilbrey	Well No. 1	Unit Letter I	Section 19
		Township 19S	Range 38E.
Date Work Performed 8-27-63	Pool Wildcat	County Lea	

THIS IS A REPORT OF: (Check appropriate block)

- ☐ Beginning Drilling Operations
 ☐ Casing Test and Cement Job
 ☒ Other (Explain): **Perforating and treating.**
- ☐ Plugging
 ☐ Remedial Work

Detailed account of work done, nature and quantity of materials used, and results obtained.

Perforated 5½" casing with crack jets, with 1 shot each per following intervals: 4176', 4219.5', 4231', 4245', 4252', 4261', 4431'.

8-28-63" Set Halliburton straddle packers at 4426-4436. Treated with 500 gallons mud acid. Recovered water.

Set permanent type bridge plug at 4400'.

8-29-63: Treated Grayburg section, 4205-4264', with 500 gallons mud acid. Test on September 8-9, 1963, pumped 119 barrels fluid in 24 hours, of which 46 barrels was oil and 73 barrels water.

Witnessed by	Position	Company
--------------	----------	---------


FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

ORIGINAL WELL DATA

D F Elev.	T D	P B T D	Producing Interval	Completion Date
Tubing Diameter	Tubing Depth	Oil String Diameter	Oil String Depth	
Perforated Interval(s)				
Open Hole Interval		Producing Formation(s)		

RESULTS OF WORKOVER

Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPD	GOR Cubic feet/Bbl	Gas Well Potential MCFPD
Before Workover						
After Workover						

OIL CONSERVATION COMMISSION		I hereby certify that the information given above is true and complete to the best of my knowledge.	
Approved by 	Name Nolan Gardner		
Title	Position Bookkeeper		
Date	Company Martin Yates, III		