

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPlicate
(Other instructions on reverse side)Form approved.
Budget Bureau No. 42-R1424.
5. LEASE DESIGNATION AND SERIAL NO.LC-069944
6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill on, to deepen, or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. WELL ☐ GAS WELL ☐ OTHER ☒ DRY HOLE

2. NAME OF OPERATOR
PAN AMERICAN PETROLEUM CORPORATION

3. ADDRESS OF OPERATOR
Box 68, Hobbs NM 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See back space 17 below.)
At surface

660' FSL x 1984.9' FWL Sec 5 (Unit N SE 1/4 SW 1/4)

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GH, etc.)
3565 R D T3

7. UNIT AGREEMENT NAME
Little Eddy Unit

8. FARM OR LEASE NAME

9. WELL NO.
1

10. FIELD AND POOL, OR WILDCAT
WILDCAT

11. SEC., T., R., M., OR BLE. AND
SURVEY OR AREA
33
5-20-86 NMPM

12. COUNTY OR PARISH
LEA

13. STATE
NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Physical abandonment of hole was effected 7-29-66. However, final cleanup of location has been delayed, continues to be delayed due to the surface owner's refusal to let us cut & dry up the pits.

As operations were performed as follows:

5 1/2" casing shot at intervals 7748, 7009, 6517, 6011, 5539 and pulled. Spotted 50 sx cement plug in & cut 1" 5 1/2" casing stub.
9 7/8" casing shot at 5565, 2022 and shot & pulled from 1903.
800 24 plug set from 2904 - 1050.
10 24 plug at surface and erected P & U marker.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

DATE

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

APPROVED

AUG 15 1967

A. H. BROWN
DISTRICT ENGINEER

*See Instructions on Reverse Side

6+ - 25 25-14
1- 25 25-14
1- 25 25-14
1- 25 25-14
1- 25 25-14
1- 25 25-14