

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Enr Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 3002521687
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. E-8072
7. Lease Name or Unit Agreement Name New Mexico "DB" State
8. Well No. 1
9. Pool name or Wildcat Osudo (Atoka)
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3678' DF

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☐ GAS WELL ☒ OTHER

2. Name of Operator
Texaco Inc.

3. Address of Operator
P.O. Box 730 Hobbs, New Mexico 88240

4. Well Location
Unit Letter B : 710 Feet From The North Line and 1980 Feet From The East Line

Section 25 Township 20S Range 35E NMPM Lea County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: Casing Connections <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4-5-91

- Cellar dug out.
- Placed riser on 11 3/4" surface casing and brought to surface with valve and marker.
Placed riser on 8 5/8" intermediate casing and brought to surface with valve marker.
Placed riser on 2 7/8" surface casing and brought to surface with valve and marker.
- Filled cellar back in.

Work inspected by R.A. Sadler of the OCD before the cellar was filled back in .

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE M.C. Duncan TITLE Engineer's Assistant DATE 4-5-91

TYPE OR PRINT NAME M.C. Duncan

TELEPHONE NO. 393-7191

(This space for State Use)

APPROVED BY R. A. Sadler TITLE Chief of Division DATE 4-5-91

CONDITIONS OF APPROVAL, IF ANY: