

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Shell Oil Company	8. Farm or Lease Name East Pearl Queen Unit
3. Address of Operator P. O. Box 1509, Midland, Texas 79701	9. Well No. 56
4. Location of Well UNIT LETTER F , 1355 FEET FROM THE North LINE AND 2475 FEET FROM THE West LINE, SECTION 34 TOWNSHIP 19-S RANGE 35-E NMPM.	10. Field and Pool, or Wildcat Pearl Queen
15. Elevation (Show whether DF, RT, GR, etc.) 3710' DF	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input checked="" type="checkbox"/> Temporary Abandonment

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10-09-72 to 11-04-72

Pulled rods and pump.

Mixed and pumped 80 sx Class H cement down casing. Squeezed 29 sx cement into perforations 4725' - 4957'. Left 200' cement plug 4525 - 4725. Shut well in.

Temporarily abandoned 11-04-72.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED **A. E. Cordray** TITLE **Staff Engineer** DATE **11-8-72**

Orig. Signed by
John Runyan
Geologist

APPROVED BY _____ DATE **NOV 13 1972**

CONDITIONS OF APPROVAL, IF ANY: