

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
LG-2061, A-1375, E-1923

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT - A" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Flag-Redfern Oil Company	8. Farm or Lease Name Osudo State Com.
3. Address of Operator P. O. Box 23, Midland, Texas 79701	9. Well No. 1
4. Location of Well UNIT LETTER <u>J</u> <u>1650</u> FEET FROM THE <u>South</u> LINE AND <u>1650</u> FEET FROM THE <u>East</u> LINE, SECTION <u>18</u> TOWNSHIP <u>20S</u> RANGE <u>36E</u> NMPM.	10. Field and Pool, or Wildcat N. Osudo (Morrow)
15. Elevation (Show whether DF, RT, CR, etc.)	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐
OTHER ☐

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOB ☐
OTHER Set 5" Liner ☒

ALTERING CASING ☐
PLUG AND ABANDONMENT ☐
OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Drilled 6 1/4" hole from 10,783' to T.D. of 11,700'. Ran 27 jts (1128') of 5" O.D., 17.93#/ft, N-80, Hydril Flush Joint Liner. Bottom of liner at 11,665', top of liner at 10,537'. Cemented w/225 sx Class "H", 0.8% Halad 22A, 0.4% CFR-2, 5# KCl per sack. Preceded cement with 16 bbls SAM-4 Spacer. Cement job complete at 4:40 A.M., 1-21-76. Reversed out est 75 sx cmt. Ran 2-3/8", 4.7#, N-80 tbg to 11,650'. Perforated and treated well. Tested on choke. Shut well in on 3-9-76. Present status - SI.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>John A. Swendig</u>	TITLE <u>Petroleum Engineer</u>	DATE <u>6-10-76</u>
APPROVED BY <u>Ray Sexton</u>	TITLE <u>Asst. L. Supv.</u>	DATE <u>6-10-76</u>
CONDITIONS OF APPROVAL, IF ANY:		