	-			
NO. OF COPIES RECEIVED			Form C-103	
DISTRIBUTION			Supersedes Old C-102 and C-103	
SANTA FE	NEW MEXICO OIL CONS	ERVATION COMMISSION	Effective 1-1-65	
FILE				
U.S.G.S.			5a. Indicate Type of Lease	
LAND OFFICE			State Fee X	
OPERATOR			5. State Oil & Gas Lease No.	
C	IDDY NOTICES AND DEPORTS ON	WELLS		
(DO NOT USE THIS FORM FOR	DRY NOTICES AND REPORTS ON I proposals to drill or to deepen or plug b Ication for permit -" (form C-101) for suc	WELLS Mack to a different reservoir. M proposals.)	<u> </u>	
	ICATION FOR PERMIT - (FORM C-TOT) FOR SOC		7. Unit Agreement Nam e	
	OTHER-			
2. Name of Operator			8. Farm or Lease Name	
Doyle Hartman			Cities - Laughlin	
3. Address of Operator			9. Well No.	
508 C & K Petroleum Bldg; Midland, Texas 79701			1	
4. Location of Well			10. Field and Pool, or Wildcat	
J	2310 FEET FROM THE South	LINE AND 2310 FEET FROM	Eunice-Monument	
[$\mathbf{\mathcal{A}}$	
East	ECTION 5 TOWNSHIP 20-	S RANGE 37-E NMPM.		
THE LINE, 3			VIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII	
15. Elevation (Show whether DF, RT, GR, etc.)			12. County	
AIIIIIIIIIIIIIIIIII	<u>3562 G. L</u>	•	Lea <u>AIIIIIII</u>	
16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data				
NOTICE O	REPORT OF:			
	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT	
TEMPORARILY ABANDON	CHANGE PLANS	CASING TEST AND CEMENT JOB		
PULL OR ALTER CASING		OTHER		
OTHER]		
17. Describe Proposed or Complete	ed Operations (Clearly state all pertinent det	ails, and give pertinent dates, including	estimated date of starting any proposed	

work) SEE RULE 1103.

Drilled well to a total depth of 3750 feet. Ran 102 jts (3759 feet) of 5 1/2 0.D., 15.5 lb/ft, J-55 ST&C casing and landed at 3750 RKB. Cemented casing with 600 sx of API Class-C cement containing 3% Halliburton Econolite and 1/4 lb/sx Flocel followed by 475 sx of a 50-50 blend of API Class-C cement and Pozmix "A" containing 18% salt and 1/4 lb/sx Flocel. Plug down at 5:55 P.M. CST 11-11-77. Circulated 130 sx of excess cement to pit. Pressure tested casing to 1500 psi and pressure held okay.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.				
SIGNED Due Charter		DATE 11-16-77		
Orig. Signed by	SUPERVISOR LISTRICT I	NOV16E.		
APPROVED BY Dies I	TITLE	DATE		
CONDITIONS OF APPROVAL, IF ANY				