



**REPORT  
of  
SUB-SURFACE  
DIRECTIONAL  
SURVEY**

\_\_\_\_\_  
CLEARY PETROLEUM CORPORATION  
COMPANY

\_\_\_\_\_  
FELMONT FEDERAL WELL NO.1  
WELL NAME

\_\_\_\_\_  
LEA COUNTY, NEW MEXICO  
LOCATION

<u>JOB NUMBER</u>	<u>TYPE OF SURVEY</u>	<u>DATE</u>
WT-278 G-1286	Gyroscopic Multi Shot	2-11-78
WT-278 S-1285	Magnetic Multi Shot	2-11-78
WT-278 G-1291	Gyroscopic Multi Shot	2-18-78
WT-278 S-1292	Magnetic Multi Shot	2-18-78
WT-778 S-2094	Magnetic Multi Shot	7-7-78

SURVEY BY  
Larry Massey  
James Blackledge

OFFICE  
West Texas  
West Texas

RECEIVED

SEP 21 1978

U.S. DEPARTMENT OF COMMERCE  
FEDERAL BUREAU OF INVESTIGATION