Form 9-331

| Form | Approved. | |
|-------|--------------|-----------|
| Budge | t Bureau No. | 42- D1424 |

| Dec. 1973 | Budget Bureau No. 42–R1424 |
|---|--|
| UNITED STATES | 5. LEASE |
| DEPARTMENT OF THE INTERIOR | LC-031736-a |
| GEOLOGICAL SURVEY | 6. IF INDIAN, ALLOTTEE OR TRIBE NAME |
| SUNDRY NOTICES AND REPORTS ON WELLS | 7. UNIT AGREEMENT NAME |
| (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.) | CA-4659 |
| | 8. FARM OR LEASE NAME |
| 1. oil gas well other | Gillully Federal Gas Com. |
| 2. NAME OF OPERATOR | 9. WELL NO. 17 |
| Amoco Production Company | 10. FIELD OR WILDCAT NAME |
| 3. ADDRESS OF OPERATOR | Eumont Queen |
| P. O. Box 68, Hobbs, NM 88240 | 11. SEC., T., R., M., OR BLK. AND SURVEY OR |
| 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) 2200' FNL & 660' FEL, Sec. 24 | AREA |
| AT SURFACE: (Unit H SE/4 NE/4) | 24-20-36 12. COUNTY OR PARISH 13. STATE |
| AT TOP PROD. INTERVAL: | Lea NM |
| AT TOTAL DEPTH: | 14. API NO. |
| 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, | |
| REPORT, OR OTHER DATA | 15. ELEVATIONS (SHOW DF, KDB, AND WD) |
| REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: | 3540-4 GR |
| FEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE | 1 E (L) |
| FRACTURE TREAT SHOOT OR ACIDIZE TY TY TY TY TY TY TY TY TY T | -20 |
| SHOOT OR ACIDIZE | 1019 |
| PULL OR ALTER CASING | (NOTE: Report results of multiple completion or zone SUMAI's on Form 9-330.) |
| MULTIPLE COMPLETE CHANGE ZONES GEOLOGY | GICAL Sumarge on Form 9-330.) EW MEXICO |
| BANDON* | EAS |
| other) | |
| including estimated date of starting any proposed work. If well is dispersived and true vertical depths for all markers and zones pertinen Moved in Service Unit 10-6-79. Tested casing Perforated 3294'-3300', 3378'-3385', 3394'-34 3444', 3492'-3501' with 2 JSPF. Ran tubing, 2951'. Tailpipe at 3199'. Acidized with 6510 Swab tested 1 day. Fraced with 29700 gal gel' Liquid CO ₂ and 48000# 20/40 sand and 18000# 1000# rock salt with 375# Benzoic acid flakes Currently flow testing well. | with 1000# for 30 min. Test OK. 16', 3418'-3425', 3428'-3435', 3439 packer, and tailpipe. Packer set a O gals 15% HCL acid with additives. 1ed 3% KCL water and 15300 gal 0/20 sand in 3 stages. Staged with |
| ubsurface Safety Valve: Manu. and Type B. I hereby certify that the foregoing is true and correct GNED BOO DOWN TITLE ASSIST. Admin | 10-18-79 |
| | Mr |
| (This space for Federal file and fffice | e use) |
| PPROVED BY | e use) |
| IGNED BOU DAVID TITLE ASSIST. Admin. (This space for rederant that the peroved by | THE TOTAL PROPERTY OF THE PROP |
| ONDITIONS OF APPROVAL, IF ANY: | THE TOTAL PROPERTY OF THE PROP |
| ONDITIONS OF APPROVAL, IF ANY: | THE TOTAL PROPERTY OF THE PROP |
| ONDITIONS OF APPROVAL, IF ANY: | OGICAL SURVEY |