Form 9-331 (May 1963)	UNITED STATES DEPARTM T OF THE INTERIC GEOLOGICAL SURVEY	COPY TO O. C. C. SUBMIT IN TRIP <sup>9</sup> .ICATE• (Other instructle on re- verse side)	Form approved. Budget Bureau No. 42-R1424. 5. LEASE DESIGNATION AND SERIAL NO. NM 053434	
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals.)			6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
1. OL GAS WELL OTHER 2. NAME OF OPERATOR			7. UNIT AGREEMENT NAME Lea Unit	
Marathon 011 Company			8. FARM OR LEASE NAME Lea Unit Deep	
<ol> <li>ADDREAR OF OPERATOR</li> <li>P.O. BOX 2409 Hobbs, New Mexico 88240</li> <li>LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface</li> </ol>			0. WELL NO. 12 10. FIELD AND FOOL, OR WILD AT Wildcat 11. SEC., T., R., M., OB BLK. AND SUBVEY OR AREA	
1980' FN 14. permit No.	L, 990' FEL, Section 13, T-22S, R34 15. ELEVATIO'S (Show whether DF, R GR 3661.7'	4 Ε Τ, GN, etc.)	Sec 13, T20S, R34E 12. COUNTY OF PARINIE 12. STATE Lea NM	
16.	Check Appropriate Box To Indicate Na	ture of Notice, Report, or C	Other Data	
	NOTICE OF INTENTION TO:		UENT REPORT OF :	
TEST WATER S FRACTORE TRE SHOOT OR ACH REPAIR WELL (Other) 17. DESCRIBE FROPO proposed wo, nent to this v	AT MULTIPLE COMPLETE MZE ABANDON* CHANGE FLANS SED OR COMPLETED OPERATIONS (Clearly state all pertinent of rk. If well is directionally drilled, give subsurface location	Completion or Recompl	SEPATRING WEL: ALTERING CASING, ABANDONMENT* I ABANDONMENT* I face csg X of multiple completion on Well etton Report and Log form.) Including estimated date of starting any i depths for all markers and dates perti-	
7-10-79	Spudded Lea Unit Deep Well #12 at	2:00 p.m. DST.		
	7-11-79/ Drill 17 1/2" hole to 902' KB. 7-12-79 Ran 25 jts. 13 3/8", 48#/ft, H-40 csg from 36' KB to 902' KB. Cement float shoe at 900.5'. Centralizer on bottom 3 jts. Cemented 13 3/8" with 500 sx Halliburton light with 1/4# Flocele and 2% CaCl. Tailed in with 300 sx Class "C" with 2% CaCl. Circulated 135 sx to pit, plug down at 12:00 midnight 7-11-79. Bumped plug at 1000 psig W.O.C.			
7-13-79	7-13-79 Finished nippling up 13 3/8" BOP stack. Tested stack to 3000 psi, held. Tested all lines and valves to 3000 psi, held. Ran in and pressure tested csg to 1000 psi, held. Drilled out float collar and 36' cement. Pressure tested shoe joint to 1000 psi, held.			
		โก	SEGEIVED	
			JUL 17 1979	
<u></u>			S. GEOL <b>ogi</b> cal Survey Hobbs, New Mexico	
This space for	Federal or State office use)	oduction Engineer ACCEPTED FOR JUL 17	RECORD July 16, 1979	
	*See Instructions of	HUVE. JUL 17 JUL 17 JUL 17 JUL 17 JUL 17 HOBBS, NE HOBBS, NE	CAL SURVEY	

REDEIVLD JUL : 4 1973 O.C.D. HOBBS, OFFICE

•