

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-101
Revised 10-1-79

NO. OF COPIES RECEIVED	
DISTRICT OFFICE	
FIELD OFFICE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPROPRIATE FORM FOR PERMIT OR FORM C-101 FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐		2. Unit Agreement Name
3. Name of Operator Doyle Hartman		8. Farm or Lease Name R. H. Huston, Jr.
4. Address of Operator P. O. Box 10426, Midland, Texas 79702		9. Well No. 4
5. Location of Well UNIT LETTER P 330 FEET FROM THE South LINE AND 990 FEET FROM West LINE, SECTION 8 TOWNSHIP 19-S RANGE 37-E NMPS.		10. Field and Pool, or Whident Eunice Monument
11. Elevation (Show whether DF, RT, GR, etc.) 3678 G. L.		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☒	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Drilled well to a total depth of 4200'. Ran 107 jts. of 5 1/2-inch OD, 17 lb/ft, J-55, ST&C casing with float collar at 4190 and DV Tool at 3850 and landed bottom of casing string at 4200 RKB. Cemented casing in two stages with first stage consisting of 160 sx of a 50-50 blend of API Class-C cement and Pozmix "A" containing 10% salt, 1/4 lb/sx Floseal, and 5 lb/sx Gilsonite and the second stage consisting of 500 sx of API Class-C cement containing 3% Econolite and 1/4 lb/sx floseal followed by 300 sx of a 50-50 blend of API Class-C cement and Pozmix "A" containing 18% salt. Circulated 80 sx of excess cement to pit on first stage and 111 sx of excess cement to pit on second stage. Final plug down at 4:30 a.m. CST 4-26-80. Pressure tested casing to 1500 psi. Pressure held okay.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Michelle Hernandez TITLE Administrative Assistant DATE 4-28-80

APPROVED BY Orig. Signed by Jerry Sexton TITLE Dist. L. Supv. DATE APR 30 1980
CONDITIONS OF APPROVAL, IF ANY: