

N. M. OIL CONS. COMMISSION
P. O. BOX 1980
ROSBURG, NEW MEXICO 88240

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well gas well other

2. NAME OF OPERATOR
Belco Petroleum Corporation

3. ADDRESS OF OPERATOR
411 Petroleum Building Midland, Tx. 79701

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) 1980 FSL and FEL
AT SURFACE:
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

- TEST WATER SHUT-OFF
- FRACTURE TREAT
- SHOOT OR ACIDIZE
- REPAIR WELL
- PULL OR ALTER CASING
- MULTIPLE COMPLETE
- CHANGE ZONES
- ABANDON*

(other) Drilling operations

SUBSEQUENT REPORT OF:

-
-
-
-
-
-
-
-
-

RECEIVED
OCT 7 1981

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

OIL & GAS
U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

5. LEASE
NM-38465

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Federal PL 14-7

9. WELL NO.
1

10. FIELD OR WILDCAT NAME
Wildact

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 14, T20S, R32E

12. COUNTY OR PARISH
Lea Co.

13. STATE
N.M.

14. API NO.
T6077

15. ELEVATIONS (SHOW DF, KDB, AND WD)
3539 GR

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

- 9/22/81 Depth 12210'. Drilling. Lime and shale.
- 9/23/81 Depth 12305'. Drilling lime and shale.
- 9/24/81 Depth 12387'. Trip for bit #22.
- 9/25/81 Depth 12483'. Drilling. Lime.
- 9/26/81 Depth 12517'. Drilling. Lime and chert.
- 9/27/81 Depth 12630'. Drilling. Lime and shale.
- 9/28/81 Depth 12714'. Drilling. Lime and shale.
- 9/29/81 Depth 12748'. Drilling. Lime and shale.
- 9/30/81 Depth 12830'. Drilling. Shale.
- 10/1/81 Depth 12713'. Drilling. Sand and shale.
- 10/2/81 Depth 12963'. Drilling. Sand and shale.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Roger A. Chapman TITLE District Manager DATE Oct. 2, 1981

ACCEPTED FOR RECORD
ROGER A. CHAPMAN
OCT 7 1981
U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL _____