## N. M. OIL CONS. COMMISSION

Form Approved.

	BOX 1980 Budget Bureau No. 42-R1424
DEPARTMENT OF THE INTERIOR	BS, NEW MEXIGOLESSE 40 NM - 01228 - A
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON (Do not use this form for proposals to drill or to deepen or plug back reservoir. Use Form 9-331-C for such proposals.)	
reservoir. Use Form 9-331-C for such proposals.)	8. FARM OR LEASE NAME
1. oil gas k other	Federal PL 14
- Well Other	9. WELL NO.
2. NAME OF OPERATOR BELCO PETROLEUM CORPORATION	1
3. ADDRESS OF OPERATOR	10. FIELD OR WILDCAT NAME
411 PETROLEUM BLDG MIDLAND, TX	wildcat
4. LOCATION OF WELL (REPORT LOCATION CLEARLY, S	X. 79701 11. SEC., T., R., M., OR BLK. AND SURVEY OR  RESPACE 17 AREA
below.) 1980 FGL and FFI	Sec 14, T20S, R32E
AT SURFACE:	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL: AT TOTAL DEPTH:	Lea Co. NM
	14 API NO
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OR REPORT, OR OTHER DATA	
the strip on other bank	15. ELEVATIONS (SHOW DF, KDB, AND WD) 3539 GR
REQUEST FOR APPROVAL TO: SUBSEQUENT REPO	1 222 GK
TEST WATER SHUT-OFF	
FRACTURE TREAT	
REPAIR WELL	
PULL OR ALTER CASING	(NOTE: Report results of multiple completion or zone change on Form 9-330.)
MULTIPLE COMPLETE	
ABANDON*	
(other) Drilling operationsxx	
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS including estimated date of starting any proposed work measured and true vertical deaths for all markets with the contract of th	(Clearly state all pertinent details, and give pertinent dates, and it is directionally drilled, give subsurface locations and ones pertinent to this work.)*
28/81 Repairing rig engine.	ones pertinent to this work.)*
	Most as to 1500#
MW 9.5.	Test csg to 1500#. OK. Test BOP.
7/81 Depth 11222'. Circ.	
<u> </u>	intonvol 11074 13000
Flowing at 25 psi thru ¼" ck	interval 11074-11222'. GTS in 22 m
O /O 1	
9/81 Depth 11229'. Drilling. Flo 10/81 Depth 11310'. Drilling.	owed gas ARO 37 MCFD. FTP 27#.
	1975 (2) EX (2)
11/81 Depth 11373'. Drilling.	
12/81 Depth 11441'. Trip for bit.	SEP 25 1001
13/81 Depth 11504'. Drilling.	TOTAL MOLIBOL VIII
Subsurface Safety Valve: Manu. and Type	OH & GAS
18. hereby certify that the foregoing is true and correct	U.S. GEOLOGICAL SURVEY ROSWELL, NEW MEXICO
SIGNED ACCOUNTINE DIST	trict Manager 9-22-81
A. CHAPMA	
This space for Federa	al as Change

U.S. GEOLOGICAL SURVEY ROSWELL, NEW MEXICO

APPROVED BY SED 7 CHEST