

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

WATER CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. V-48

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name ---
2. Name of Operator MORRIS R. ANIWEIL	8. Farm or Lease Name State SX
3. Address of Operator P. O. Box 2010, Hobbs, NM 88240	9. Well No. 1
4. Location of Well UNIT LETTER J 1980 FEET FROM THE South LINE AND 1980 FEET FROM THE East LINE, SECTION 36 TOWNSHIP 19-S RANGE 37-E NMPM.	10. Field and Pool, or Wildcat East Monument Paddock
15. Elevation (Show whether DF, RT, GR, etc.) 3595' GR	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugged and abandoned as follows:

1. Spotted 100 sx plug 5390' to 4530'.
 2. Spotted 50 sx plug 3621 to 3421'
 3. Spotted 35 sx plug 1550 to 1450'
 4. Spotted 10 sx surface plug.
 5. Set marker
- Plugged and abandoned Aug 9, 1983.
Pulled 3572' 4½" casing when collapsed & parted.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED James Hilla TITLE Agent DATE Aug 10, 1983

APPROVED BY Ronald M. Cuthbert TITLE OIL & GAS INSPECTOR DATE SEP 8 1983

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

AUG 12 1983

C.C.D.
HOBBS OFFICE