Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993

5. Lease Designation and Serial No.

| | | NM-13280 |
|--|---|---|
| SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals | | 6. If Indian, Allottee or Tribe Name |
| SUBMIT IN TRIPLICATE | | 7. If Unit or CA, Agreement Designation |
| 1. Type of Well | | |
| X Oil Gas Well Other | | 8. Well Name and No. |
| 2. Name of Operator | | Smith Ranch "11" Fed. #1 |
| Hondo Oil & Gas Company | | 9. API Well No. |
| 3. Address and Telephone No. | | 30-025-31255 |
| P. O. Box 2208, Roswell, NM 88202 (505)625-6732 | | 10. Field and Pool, or Exploratory Area |
| 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) | | Teas Bone Springs |
| 2310' FSL & 900' FWL; Sec.11-T20S-R33E | | 11. County or Parish, State |
| thron L | | Lea Co., NM |
| | ((s) TO INDICATE NATURE OF NOTICE, REPO | DRT, OR OTHER DATA |
| TYPE OF SUBMISSION TYPE OF ACTION | | |
| | | Change of Plans |
| ☐ Notice of Intent | Abandonment Recompletion | New Construction |
| X Subsequent Report | Plugging Back | Non-Routine Fracturing |
| | Casing Repair | Water Shut-Off |
| Final Abandonment Notice | Altering Casing | Conversion to Injection |
| | X Other Ran 8 5/8" & $5\frac{1}{2}$ " cs | |
| | ran DST. | (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) |
| @ 3531' & ECP @ 35' No circulation dur opening bomb & op DV & WOC. Cmtd 2nd Class "C". After cmt. job did not c 7/09/91 Closed DV tool w/60' perf'd 4 sqz holes 1959'-1960' to get holes @ 1959'-1960 11:00 p.m. 7/9/91 Ran temp log & four 7/10/91 Perf'd 4 sqz holes w/1800sx Lite + 460 | @ 1589'-1590' (.36"). Cmtd thru 8 5/ Osx Class "C" Neat + 200sx Class "C". | tailed in w/200 sx Class "C' 7:15 a.m. 7/8/91. Drop 11 3/4 hrs circ thru. Tailed in w/100sx irc. Good circ. throughout Ran temp. log TOC @ 1970' 5/8" csg sqz holes @ Cmtd 8 5/8" csg thru sqz ass "C". Plug down @ d by Jack Johnson w/BLM. [8" sqz holes @ 1589'-1590' Plug down @ 8:15 p.m. |
| | w/300sx. WOC 18 hrs. NU BOP stack. press. tested per ${f f}$ s ${f t}$ o 500psi, O.K. (| |
| | Title Regulatory Secretary | Date 07/29/91 |
| (This space for Federa) or State office we) Approved by | AN Title | Date |

Form 3160-5
Page 2
NM-13280
Smith Ranch "11" Fed. #1
30-025-31255
Sec.11-T20S-R33E
Lea Co., NM
Hondo Oil & Gas Company

13. cont.

7/20/91 DST #1 - 9417'-9465' (Bone Springs Sand).

7/21/91 T.D. 9700'.

7/22/91 Ran GR-Spectral Density Duel Spaced Neutron Log, GR-DLL-MSFL & GR-Dipmeter.

7/23/91 Ran $5\frac{1}{2}$ " 17# N-80 LTC csg, FS @ 9700', FC @ 9615', DV tool @ 7502', cmtd lst stage w/500 gals mud flush + 500 gals Superflush 102 + 600 sx Class "H". Plug down @ 12:15 p.m. 7/23/91. Dropped opening bomb & opened DV tool & circ l19 sx of cmt to surface, circ 4 hrs cmtd 2nd stage w/450sx Howco Lite followed by 150sx Class "H". Plug down @ 5:15 p.m. 7/23/91 w/2200psi. Rig released @ 12:00 midnight on 7/23/91.