RECEIVED Form 3160-5 (June 1990) DEPARTMENT OF THE INTERIOR NOV 23 10 30 MI 'HUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. ARU- Use "APPLICATION FOR PERMIT—" for such proposals		FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993 5. Lease Designation and Seriel No. NM-039256; 6. If Indian, Alloitee or Tribe Name NONE
SUBMIT IN TRIPLICATE		7. If Unit or CA, Agreement Designation NONE
Oil Ges Other		8. Well Name and No. Silver Federal Lease No. 2
2. Name of Operator Thomas Ray Sivley		9. API Well No.
3. Address and Telephone No. 6509 Wilton Ave.		30-025-31441
Fort Worth, TX 76133 4. Location of Well (Footage, Sec., T., R., M., or Survey Descrip	Telephone: (817)292-3283	10. Field and Pool or Exploratory Area Lynch, Seven Rivers, Yates
1. Location of Well (rootage, Sec., 1., K., M., or Survey Descrip	1600 FEL and 1500 FSL, Section 28, Township 20S, Range 34E, Unit J, Lea County, New Mexico	11. County or Par sh, State Lea County, New Mexico
12. CHECK APPROPRIATE BOX	(s) TO INDICATE NATURE OF NOTICE, REPO	ORT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION	
Notice of Intent	Abendonment	Change of l'lans
Subsequent Report	Recompletion Plugging Back Casing Repair	New Construction Non-Routir e Fracturing Water Shu-Off
Final Abandonment Notice	Altering Casing X Other <u>Drilling Report</u>	Conversion to Injection Dispose Weiter (Note: Report results of multiple completion on Well Completion or Recompletion Report and Leg form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent datas, including estimated data of starting and proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

This well Spudded: 9:00AM, 11/10/91. 12.25" Hole drilled to 1680' on 11/13/91and 1680 Ft. of 8-5/8" OD J55 New Smls Casing was landed at 1672 Ft. and cemented with 600 sacks of Halliburton Premium Plus, with: 10 lbs (10#) Gilsonite, .25 lbs (1/4#) Flocele, Tailed with: 200 sacks Premium Plus, with .25 lbs (1/4#) Flocele and 2% Anhydrous Calcium Chloride. Plug down at 2:45 P.M. Cement circulated. Calculated Volume to circulate: 941 Cu. Ft.; Circulated 291 Sacks to pit.

Cementing procedures witnessed by: Andy Cortez, Petroleum Technician, BLM, Lea County Inspection and Enforcement.

On 11/14/91- Tested Blind Cams (1/2 hr. @1000PSI)-OK. Tripped in. Tested Pipe Rams (1/2 hr. @1000PSI)- OK. Drilled plug and Float. Drilling was resumed. Drilled thru; Top of Salt 1740'. Drilled thru; Base of Salt 3300'.

I hereby cartify that the foregoing is trug and correct.	TitleOperator	Date November 18, 1991
(This space for federal or State office use) Approved by Conditions of approval, if any:	Title	Data
le 18 U.S.C. Section 1001, makes it a crime for any person knewingly representations as to any matter within its jurisdiction.	and willingly to make to and department or agency o	f the United States and false, fictitious or fradulent states