

NMGSAU #624 - CONTINUED - PAGE 2

N.D. 11" 3M X 2-9/16" X 2-7/8" SLIPS ADAPTER FLANGE FR. HYDRIL BOP. KNOCKED & CLEANED SNOW OUT OF DERRICK. MIRU SERVICE EQUIP. TIH W/REDA SUBMERSIBLE PUMP EQUIP. CONSISTING OF: LOWER TANDEM MOTOR, UPPER TANDEM MOTOR, PROTECTOR, LOWER TANDEM PUMP, UPPER TANDEM PUMP, 1 JT. 5-1/2" 8RD 17# CSG., 5-1/2" 8RD CHK. VALVE, 1 JT. 5-1/2" 8RD 17# CSG., 5-1/2" 8RD DRAIN VALVE, & 19 JTS. 5-1/2" 8RD 17# CSG. NOTE: 5-1/2" CSG. USED AS TBG. TIH W/10 JTS. 5-1/2" 8RD 17# CSG., & 36 JTS. 5-1/2" 8RD 17# CSG. W/TK-99 IPC. RD SERVICE EQUIP. N.D. 10" 900 HYDRIL BOP. INSTALLED 11" 3M X 5-1/2" 8RD NATIONAL TUBING HEAD W/REDA CABLE PACK-OFF & LANDED 5-1/2" CSG. INSTALLED 5-1/2" 8RD NIPPLE X 7-1/16" 3M ADAPTER FLANGE & 7-1/16" 3M X 7-1/16" 3M CAMERON MASTER VALVE. INSTALLED DISCHARGE LINE OFF MASTER VALVE. STARTED PUMP & HAD FLUID TO SURFACE IN 90 SECONDS. PUMPING AT A RATE OF 26,000 BPD @ 133 AMPS. SHUT DOWN PUMP TO CLEAN PLUGGING STRAINER. LEFT PUMP DWN. TYLER WELL SERVICE & STAR TOOL RD EQUIP. & CLEANED LOCATION. NMGSAU#624 STARTED AT 1:45 P.M. ON 02-18-97. AVERAGE RATE OF 26,800 BPD, 66# TUBING PRESSURE AND 131 AMPS.