

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLI  
(Other Instructions  
reverse side)

Form Approved  
Budget Bureau No. 1004-0135  
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT--" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. UNIT AGREEMENT NAME EAST EUMONT UNIT	
2. NAME OF OPERATOR OXY USA INC.		8. FARM OR LEASE NAME	
3. ADDRESS OF OPERATOR P.O. BOX 50250 MIDLAND, TX 79710		9. WELL NO. 127	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 660 FNL 510 FWL NW-NW		10. FIELD AND POOL, OR WILDCAT EUMONT YATES 7 RVR QN	
		11. SEC. T., R., M., OR BLK AND SURVEY OR AREA SEC 12 T20S R37E	
14. PERMIT NO. 300250606400S01	15. ELEVATIONS (Show whether DF, RT, GF, etc.) 3595	12. COUNTY OR PARISH LEA	13. STATE NM

16.

Check Appropriate Box To Indicate Nature of Notices, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF  
FRACTURE TREAT  
SHOOT OR ACIDIZE  
REPAIR WELL

☐  
☐  
☐  
☐

PULL OR ALTER CASING  
MULTIPLE COMPLETE  
ABANDON\*  
CHANGE PLANS

☐  
☐  
☐  
☐  
☒

WATER SHUT-OFF  
FRACTURE TREATMENT  
SHOOTING OR ACIDIZING  
(Other)

☐  
☐  
☐

REPAIRING WELL  
ALTERING CASING  
ABANDONMENT\*

☐  
☐  
☐

(Other) TEMPORARILY ABANDON

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and five pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

TD - 3850' PBDT - 3844' PERFS - 3690' - 3807'

OXY USA INC. REQUESTS TO TEMPORARILY ABANDON THIS WELL FOR FUTURE CONVERSION TO WATER INJECTION. THE WATERFLOOD PATTERN WILL BE CHANGED FROM A 80 ACRE 5-SPOT TO A 40 ACRE 5-SPOT.

- 1) MIRU PU. TIH W/ CIBP & SET @ 3650'.
- 2) NOTIFY BLM OF CASING INTEGRITY TEST 24 HRS IN ADVANCE.
- 3) RU PUMP TRUCK, CIRCULATE WELL WITH TREATED WATER, PRESSURE TEST CASING TO 500# FOR 30 MIN.

18. I hereby certify that the foregoing is true and correct

SIGNED

*[Signature]*

TITLE

REGULATORY ANALYST

DATE

9/23/94

(This space for Federal or State office use)

APPROVED BY

(ORIG. SGD.) JOE G. LARA

TITLE

PETROLEUM ENGINEER

DATE

10/6/94

CONDITIONS OF APPROVAL, IF ANY:

See attached.

\*See Instructions on Reverse Side

OFFICE OF THE

GOVERNOR

STATE OF NEW YORK

BUREAU OF LAND MANAGEMENT  
CARLSBAD RESOURCE AREA

Temporary Abandonment of Wells on Federal Lands

Conditions of Approval

According to 43 CFR 3162.3-4-c, " No well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer".

Temporary Abandonment (TA) status approval requires a successful casing integrity test as follows:

1. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County call (505) 887-6544 ; for wells in Lea County call (505) 393-3612.
2. A bridge plug or packer shall be set at a maximum of 50 feet above any open perforations or open hole.
3. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.
4. The production casing shall be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes with a 10% allowable leak-off.

Wells that successfully pass the casing integrity test will be approved for Temporary Abandonment (TA) status for 12 months provided that the operator:

1. Submits a subsequent Sundry Notice requesting TA approval,
2. Attaches a clear copy or the original of the pressure test chart,
3. And attaches a detailed justification why the well should not be plugged and abandoned.

The TA status could be extended without another casing integrity test provided there was no leak-off during the test.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

1. A procedure to repair the casing so that a TA approval can be granted.
2. A procedure to plug and abandon the well.

29th Nov 1994

00:00:00

00:00:00