Fain approved. Addget Bureaus No. 1004-0135 Expires August 31, 1985 Form 3130-5 UNIT 'STATES SUBMIT IN TRIPLI (Novel. ber 1983) (Other Instructions) (Formerly 9-331) DEPARTMEN. OF THE INTERIOR 5, LEASE DESIGNATION AND SERIAL NO. verse side) SUNDRY NOTICES AND REPORTS ON WELLSCO Se this form for proposals to drill or to docern 8910086960 - LC031620B 6. IF INDIAN, ALLOTTEE OR TRIBE NAME (Do not use this form for proposals to drill or to deepen or plug back to a different Use "APPLICATION FOR PERMIT--" for such proposals.) 7. UNIT AGREEMENT NAME weir [≖ **EAST EUMONT UNIT** WELL OTHER 2. NAME OF OPERATOR 8. FARM OR LEASE NAME OXY USA INC. 3. ADDRESS OF OPERATOR 9. WELL NO. P.O. BOX 50250 MIDLAND, TX 79710 129 10. FIELD AND POOL, OR WILDCAT 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) **EUMONT YATES 7 RVR QN** At surface 11. SEC., T., R., M., OR BLK AND SURVEY OR AREA 660 FNL 1980 FEL NW-NE SEC 12 T20S R37E 12 COUNTY OR PARISH 14. PERMIT NO. 15. ELEVATIONS (Showwheter DF, RT, GR, etc.) 13. STATE LEA NM 300250606600S01 3592 Check Appropriate Box To Indicate Nature of Notices, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: REPAIRING WELL TESTWATER SHUT-OFF WATER SHUT-OFF PULL OR ALTER CASING ALTERING CASING FRACTURE TREATMENT MULTIPLE COMPLETE FRACTURE: TREAT ARANIYONMENT* SHOOTING OR ACIDIZING ABANDON* SHOOT OR ACIDIZE (Other) **CHANGE PLANS** REPAIRWELL (Note: Report results of multiple completion on Well TEMPORARILY ABANDON Completion or Recompletion Report and Log form.) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and five pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* TD - 3875' PERFS - 3700' - 3856 OXY USA INC. REQUESTS TO TEMPORARILY ABANDON THIS WELL FOR FUTURE CONVERSION TO WATER INJECTION. THE WATERFLOOD PATTERN WILL BE CHANGED FROM A 80 ACRE 5-SPOT TO A 40 ACRE 5-SPOT. 1) MIRU PU. TIH-W/ CIBP & SET @ 3670'.

2) NOTIFY BUM CASING INTREGRITY TEST 24 HRS IN ADVANCE.

3) RU PUMP TRUCK, CIRCULATE WELL WITH TREATED WATER, PRESSURE TEST CASING TO 500# FOR 30 MIN.

8. I hereby certify that the figregoing is true and correct			
SIGNED	Judgles	TITLEREGULATORY ANALYST	DATE 9/23/94

(This space for Federal or State office use)

APPROVED BY (ORIG. SGD.) JOE G. LAPATITLE PETROLEUM ENGINEER DATE 10/6/94 conditions of APPROVAL, IF ANY: See attached.

BUREAU OF LAND MANAGEMENT CARLSBAD RESOURCE AREA

Temporary Abandonment of Wells on Federal Lands

Conditions of Approval

According to 43 CFR 3162.3-4-c, " No well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer".

Temporary Abandonment (TA) status approval requires a successful casing integrity test as follows:

- Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County call (505) 887-6544; for wells in Lea County call (505) 393-3612.
- 2. A bridge plug or packer shall be set at a maximum of 50 feet above any open perforations or open hole.
- 3. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.
- 4. The production casing shall be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes with a 10% allowable leak-off.

Wells that successfully pass the casing integrity test will be approved for Temporary Abandonment (TA) status for 12 months provided that the operator:

- 1. Submits a subsequent Sundry Notice requesting TA approval,
- 2. Attaches a clear copy or the original of the pressure test chart,
- 3. And attaches a detailed justification why the well should not be plugged and abandoned.

The TA status could be extended without another casing integrity test provided there was no leak-off during the test.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.