

(SUBMIT IN TRIPLICATE)

Land Office Las Cruces

X			

UNITED STATES OFFICE OF
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Lease No. LC 031621 (b)
Unit NMFM

1962 JUN 15 AM 10 13

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	X
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Britt B-15 June 13, 19 62

Well No. 13 is located 660 ft. from N line and 660 ft. from W line of sec. 15

NW/4 Section 15

20S

37E

NMFM

(1/4 Sec. and Sec. No.)

(Twp.)

(Range)

(Meridian)

Monument-Tubb &

Lea

New Mexico

Weir-Elizary

(County or Subdivision)

(State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spudded 8:30 A.M. 6-10-62. Drilled to 1233'. Ran 40 jts 8-5/8" OD 24# J-55 casing. Casing set at 1233' and cemented with 360 sacks cement. Cement circulated. Plug down at 7:35 A.M. 6-11-62. WOC 24 hours. Tested casing with 1,000 lbs for 30 min. Tested O.K.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Continental Oil Company

Address Box 68

Runice, New Mexico

By _____

Title District Superintendent

USGS (3) NMOC (2) WAM File