



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Las Cruces
Lease No. _____
Unit P

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			
NOTICE OF INTENTION TO REPAIR CASING			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

September 14, 1962

3340 Pennsylvanian

Well No. 61 is located 990 ft. from S line and 990 ft. from E line of sec. 15

SE 1/4 Sec. 15 (1/4 Sec. and Sec. No.) 20-3 (Twp.) 37-5 (Range) 101PM (Meridian)

Case (Field) Lee (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 3550 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

The 3340 Pennsylvanian is presently TSD. An attempt was made on July 3, 1962, to fish the pump from this well. During the process, the 7" casing WAS FOUND TO BE parted in two or more places. We propose to remove approximately 2800' of existing casing by cutting, fishing and milling. It will then be replaced with 7" OD 23# J-55 casing utilizing a casing bowl.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Continental Oil Company

Address Box 68

San Jose, New Mexico

By _____

0/3 LOGS; MDC-2; HAN; File Title District Superintendent
Per Am-10a-3; At-10a-2; Calif. Oil Co.-Houst, Mid-land.