Submit 3 Copies To Appropriate District Office	State of New Mexico		V	Form C-103
District I	Energy, Minerals and Natural Resources			Revised March 25, 1999
1625 N. French Dr., Hobbs, NM 88240 District II		WELL API NO.		
B11 South First, Artesia, NM 88210	OIL CONSERVATION DIVISION		30-025-06137 5. Indicate Type of Lease	
<u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410			1	_ _
<u>District IV</u> Santa Fe, NM 8/505		STATE I		
2040 South Pacheco, Santa Fe, NM 87505			6. State Oil & 0	Gas Lease No. State USC #
	S AND REPORTS ON WELLS		7. Lease Name o	r Unit Agreement Name:
(DO NOT USE THIS FORM FOR PROPOSAL	S TO DRILL OR TO DEEPEN OR PL	UG BACK TO A		ome rigicoment ivalie.
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			State H-1	- 7
1. Type of Well:			Diale Hai	1
Oil Well 🖾 Gas Well 🗆 Other				
2. Name of Operator			8. Well No.	
Bili Gas Operations				2
3. Address of Operator			9. Pool name or	
11507 County Rd 52 West, Midland, Tx, 79707 4. Well Location			Eunice	Monument
4. Well Location	·			
Unit Letter \mathcal{D} :	330 feet from the $\sqrt{}$	line and	330 feet fro	m the line
Sint Botter	icet hom me 14	inte and	r 70 leet mo	m theline
Section 17	Township 205 Ra	inge 37E	NMPM	County Lea
	0. Elevation (Show whether D.			County / Ca
	3541 44			
11. Check App	propriate Box to Indicate N	ature of Notice, I	Report or Other	Data
			SÉQUENT RE	
PERFORM REMEDIAL WORK 🔲 F	LUG AND ABANDON 🔲	REMEDIAL WORK	<	ALTERING CASING
TEMPODADUV ADANDON				
TEMPORARILY ABANDON C	CHANGE PLANS	COMMENCE DRII	LING OPNS. 🔲	PLUG AND
PULL OR ALTER CASING .	MULTIPLE	CASING TEST AN	ın (ABANDONMENT
	COMPLETION	CEMENT JOB		
OTHER			. 2	.1.4
OTHER:		OTHER: Wel	1 Pulling	
12. Describe proposed or completed	operations. (Clearly state all per	tinent details, and g	ive pertinent dates,	including estimated date
of starting any proposed work). S or recompilation.	EE RULE 1103. For Multiple (Completions: Attach	wellbore diagram	of proposed completion
or recompliation.				
In the routing cours	e of placing well back	con productio	ы .	
In the routine course of placing well back on production:				
1) Junk was found in the hole (old tubing?) from 3542' to PBD 3680'				
Donly 11' of junk was recovered, leaving top of junk at 3553'.				
(3) (asing was tested to 300 # from 3373' to Surface - tested OK.				
(A) Rode (1) - last 1 - 1/2 -				
@ Rods/Hog laid down with well temp. SI awaiting further evaluation.				
		•		
				,
XI I I I I I I I I I I I I I I I I I I				
I hereby certify that the information ab	ove is true and complete to the l	est of my knowledg	e and belief.	
SIGNATURE A	SIGNATURE TITLE Owner			DATE 9/4/00
C - L			_DATE	
Type or print name Grea Sh	nort		Telen	hone No. (915) 563-1358
(This space for State use)		······································	10100	707-17
		Á.		
APPPROVED BY	TITLE			DATE
Conditions of approval; if any:				**************************************

->, ___