

HUMBLE OIL & REFINING COMPANY'S
NEW MEXICO OPERATING FIELD.

N. E. 1/4 of Section 17, Township 20, South, Range 37- East,
Deer County, New Mexico.

DEVIATION SURVEY

Acid bottle test at 500'---deviation 1/2 of 1 degree
Acid bottle test at 1500'---deviation 1 degree
Acid bottle test at 2000'---Hole straight
Acid bottle test at 2500'---Hole straight

DRILL TEST RESULTS

NONE