

**HUMBLE OIL & REFINING CO.
HUBERT? NEW MEXICO.**

N. M. WATER P-4

**S.W. 1/4 of Section 17, Township 20-South, Range 37 East
Lea County, New Mexico.**

Deviation Surveys

acid bottle test at 500'	deviation 1 degree.
acid bottle test at 1000'	deviation 0 degree.
acid bottle test at 1500'	deviation 0 degree.
acid bottle test at 2200'	deviation 0 degree.
acid bottle test at 2800'	deviation 0 degree.

Well Stem Tests

NOTE.