

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office

Lease No.

Unit

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF STOPPING OR ACIDIZING.....	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

P.P.Co.
Hobbs No. 1

Midland, Texas, August 4, 1937

Well No. One is located 660 ft. from N line and 660 ft. from E line of sec. 18 ^{SW/4}

SW/4 Section 18 20-S 37-E N. M. P. M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)

Monument Lea New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3574 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

T. D. 3870. Acidized with 5000 gallons Dowell "X" solution and 5000 gallons Dowell "XX" solution, thru tubing, treating formation from bottom of 7" casing (3778') to total depth, July 30, 1937

Production before treating. 4 Hr. Test 154.99 bbls. oil
Production after treating. 6 Hr. Test 258.00 bbls. oil

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Phillips Petroleum Company

Address Box 1390, Midland, Texas

By /s/ Earl Griffin

Title District Supt.