

5. LEASE DESIGNATION AND SERIAL NO.

LC-031621(b)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Hobbs

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

Eunice Monument Gb/SA

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

18, 20-S, 37-E

12. COUNTY OR PARISH 13. STATE

Lea

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Phillips Petroleum Company (663680)

3. ADDRESS OF OPERATOR

Room 401, 4001 Penbrook, Odessa, Texas 79762

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

Unit L, 1980' from south and 660' from west lines.

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3573' DF

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) Perforate & acidize open hole

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

9-9-81: MI Tyler DDU, pld rods & tbg. Ran sand pmp to 3865', BO ran GR-CNL caliper CCL logs from 3865'-2000'. Perfd OH w/Tornado frac charges. 3774-76, 3780-82, 3786-88, 3792-96, 3800-12, 3816-26, 3830-38, 3840-46, 3850-54

9-10-81: Ran 2-7/8" tbg. RTTS pkr, set tbg @ 3830', pkr @ 3710', Gold Star trtd OH 3767-3865 w/5000 50% NeFe HCl, flshd w/26 bbls 2% KCl wtr.

9-11,12

13-81: Pld RTTS pkr & tbg. Set 2-7/8" tbg OE @ 3830'. SN @ 3829'. Ran 2" x 1-1/2" x 12' pmp @ 3829'. Hung well on, RD Tyler unit.

9-15-81: Pmpd 24 hrs, 35 BO, 119 BW, GOR: 237, from open hole 3767-3865'. Returned well to production status.

BOP Equip: Series 900, 3000#, double, w/1 set pipe rams and 1 set blind rams manually operated.

18. I hereby certify that the foregoing is true and correct

SIGNED

W. J. Mueller

TITLE

Sr. Engineering Specialist

DATE

9-18-81

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD

DATE

*See Instructions on Reverse Side

SEP 29 1981

U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO