

Indian Agency.....

(SUBMIT IN TRIPLICATE)

U. S. Land Office... Las Cruces

## UNITED STATES

Lease or permit No. 0-31621

Allottee.....

## DEPARTMENT OF THE INTERIOR

Lease No.....

## GEOLOGICAL SURVEY

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....		SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	<b>X</b>	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....		SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....		SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....		SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

March 23, 1937

MexicoWell No. 1 is located 330 ft. from N line and 330 ft. from E line of sec. 18NE 1/4 Sec. 18 29S 37E N.M.P.M.  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)Monument Lea New Mexico  
(Field) (County or Subdivision) (State or Territory)The elevation of the derrick floor above sea level is 3564 ft.

## DETAILS OF WORK

(State names of and expected depths of objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

TD 3788 - Lime - Set 7" OD 24# SS Casing at 3781'9". Cement with 300 sacks fibrel.

Test for casing shut-off will be made noon, March 25th.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Phillips Petroleum CompanyAddress Box 1390 Midland, TexasBy /s/ Earl GriffinTitle Dist. Supt.